


**ANACONDA Copper Company**

New Mexico Operations  
P.O. Box 638  
Grants, New Mexico 87020  
505/876-2211



May 2, 1980


Mr. Ed Sandell  
Area Mining Supervisor  
United States Geological Survey  
P. O. Box 26124  
Albuquerque, New Mexico 87125

Dear Mr. Sandell:

The following information is being submitted in accordance  
with the Jackpile Mine Reclamation Sampling Plan:

1. Radiological Analysis of reclamation site soils.
2. Surface gamma emission from reclaimed sites.
3. Radon exhalation values from reclaimed sites.

Sincerely,

  
Meade A. Stirland, Manager  
Environment, Health & Safety

mls

cc: RDL  
ECL  
CES  
File